



United States
**CONSUMER PRODUCT
SAFETY COMMISSION**

ECR International Recalls Gas-Fired Hot Water Residential Boilers Due to Carbon Monoxide Poisoning Hazard



Recalled Dunkirk gas-fired hot water residential boiler

**Name of Product:**

Gas-fired hot water residential boilers

Hazard:

The recalled residential boilers can be missing the flue inspection cover plate, posing a risk of exposure to combustion flue gasses and a carbon monoxide poisoning hazard.

Remedy:

Repair

Recall Date:

July 13, 2023

Units:

About 1,745

Consumer Contact

ECR International at 800-241-5501 from 8 a.m. to 4:30 p.m. ET Monday thru Friday, by email at ecrcustomerservice@ecrinternational.com, or online at www.ecrrecall.com or www.ecrinternational.com and click on “Recall” for more information.

Recall Details

Description:

This recall involves gas-fired hot water residential boilers with brand names Dunkirk, Utica Boilers, Utica Heating, Pennco, Green Mountain and Columbia and with model numbers DXL-K, MGB-K, UH15B-K, 15B-K, GMGW-K, or MCB-K respectively. The boilers are blue and/or gray in color, 32-inches tall, 13- to 27-inches wide and 26-inches deep. The model and serial numbers are located on the boiler rating plate in the front left corner of the top panel. The following models and serial numbers are included in the recall:

Brand Name	Boiler Model Number	Serial Number Range	
Dunkirk	DXL-K:		
	DXL-060K	Serial Number Range:	
	DXL-095K		
	DXL-120K		392201652s thru
	DXL-150K		402202738s
	DXL-175K		012302567s and 012302571s
	DXL-205K		
DXL-235K			

MGB-K:		
Utica Boilers	MGB-060K	Serial Number Range:
	MGB-095K	402200481s thru
	MGB-120K	402202693s
	MGB-150K	012302268s thru
	MGB-175K	012302566s
	MGB-205K	
	MGB-235K	

MCB-K:		
Columbia	MCB-060K	
	MCB-095K	Serial Number Range:
	MCB-120K	402201449s thru
	MCB-150K	402202214s
	MCB-175K	
	MCB-205K	
	MCB-235K	

UH15B-K:		Serial Number Range:
Utica Heating	UH15B-060K	392201654s thru
	UH15B-095K	402202800s
	UH15B-120K	012302274s thru
	UH15B-150K	012303099s

UH15B-175K

UH15B-205K

UH15B-235K

15B-K:

15B-060K

15B-095K

15B-120K

15B-150K

15B-175K

15B-205K

15B-235K

Pennco**Serial Number Range:**

392202597s thru

402202806s

012301918s thru 012303055s

GMGW-K:

GMGW-060K

GMGW-095K

GMGW-120K

GMGW-150K

GMGW-175K

GMGW-205K

GMGW-235K

Green**Mountain****Serial Number Range:**

392201653s thru

402202686s

012301924s thru 012301961s

Remedy:

Consumers should immediately stop using the recalled gas-fired hot water residential boilers and contact ECR International to arrange for a free inspection and repair in the form of a free installation of the inspection cover plate, if missing.

Incidents/Injuries:

None reported

Sold At:

Wholesale distributors mainly in the Midwest and Northeast from December 2022 through May 2023 for between \$2,000 and \$4,000.

Manufacturer(s):

ECR International Inc., of Utica, New York

Manufactured In:

United States

Recall number:

23-243

Fast Track Recall

Note: Individual Commissioners may have statements related to this topic. Please visit www.cpsc.gov/commissioners to search for statements related to this or other topics.

Recall Complaint

If you are experiencing issues with a recall remedy or believe a company is being non-responsive to your remedy request, please use the form below and explain the situation to CPSC.